OUT58202

12 APR 1966

pitxx.1

CB<mark>AD</mark> CSA-LO

Advance copy

SECRET 112337Z

1966 ATR 11 23 49 Z

6893

25X1

- 1. CAMERA B 15 WAS USED IN MISSION 8084 FLOWN ON 8 APRIL 1966. PROCESSING WAS ACCOMPLISHED BY BARKSDALE.
 - 2. ORIGINAL NEGATIVE:
- A. THE EXPOSURE WAS ADEQUATE AND RESOLUTION IS POOR.

 THE POOR RATING IS GIVEN BECAUSE OF PHOTOGRAPHY IS 100 PERCENT

 AFFECTED BY ATMOSPHERIC CONDITIONS.
- B. 9R SIDE: EDGE STATIC IS PRESENT ALONG THE OUTBOARD EDGE. ROLLER CHATTER OCCURS ALONG BOTH EDGES INTERMITTENTLY. AN EMULSION ABRASION IS NOTED ON FRAME 631. A HEAT SPLICE IS LOCATED BETWEEN FRAMES 918/919. HANDLING MARKS ARE PRESENT AT ALL HEAT SPLICES. A MANUFACTURING SPLICE IS LOCATED THROUGH FRAME 1314.
- C. 9L SIDE: THE FIRST FEW FRAMES CONTAINED NUMEROUS

 MINUS DENSITY DOTS WHICH WERE APPARENTLY CAUSED BY FOREIGN

 PARTICLES. FRAMES ØØØØ THROUGH ØØ37 CONTAIN A ROW OF MINUS

 DENSITY DOTS 1.5" APART 2.5" FROM THE INBOARD EDGE OF THE FILM.

 STARTING AGAIN IN FRAME 132Ø, THESE DOTS ARE LOCATED 5.7" FROM

 THE INBOARD EDGE AND CONTINUE THROUGHOUT THE BALANCE OF THE MISSION.

 MINOR SCRATCHES AND PINHOLES WERE DETECTED IN FRAMMES 299, 9ØØ, AND

 1774. A MANUFACTURING SPLICE IS LOCATED IN FRAME 1579. FRAMES

 18ØØ THROUGH 2Ø99 WERE TITLED "R" AND THE TITLING CORRECTED TO

 READ "L".

ercup i Exeluted from automotic temperating and teclassification

SECRFT

- D. BOTH SIDES: NO COMMENT.
- E. THERE WERE NO MAJOR MALFUNCTIONS ALTHOUGH THE DATA

 CHAMBER COUNTER STUCK AT NUMBER 1790 AND REMAINED IN THAT POSITION

 FOR THE BALANCE OF THE MISSION. THE TITLED FRAMES ARE NUMBERED 0000

 THROUGH 2351.
 - 3. POSITIVE:
 - A. THE PI SUITABILITY IS POOR DUE TO ATMOSPHERIC CONDITIONS.
 - B. PRINTING AND PROCESSING ARE GOOD.
 - C. CLOUDS OBSCURE 85 TO 90 PERCENT OF THE MISSION.

SECRET

/END OF MESSAGE/